

HARTZELL

PROPELLER LOGBOOK

AirMart.com
AIRCRAFT SALES & BROKERAGE

PROPELLER MODEL HC-CZYR-1BF/F7495

PROPELLER S/N N54070B

LOGBOOK # _____

Da



Date: 10/4/18 N176DS S/N: 40.376
Propeller: HC-C2YR-1BF/F7495S S/N: NS4070B
Total Time: 0.0 Tach 3488.7 Hobbs: 4791.2

MX Aero Global LLC
2901A E. Spring St. Long Beach, CA 90806
Main: 562.366.4806
Cell: 562.881.5345

1. Installed prop IAW STC # SA01850CH. See Form 337 this date.

I certify the above work was performed IAW DA40 AMM and is in airworthy condition.

Authorized Signature

David Seastead AP3492477 IA



Date: 11/2/18 N176DS S/N: 40.376
Propeller: HC-C2YR-1BF S/N: NS4070B
Total Time: 28.9 TACH: 3517.6 Hobbs: 4875.7

MX Aero Global LLC
2901A E. Spring St. Long Beach, CA 90806
Main: 562.912.4263
Cell: 562.881.5345

1. Performed 100Hr inspection using DA40 AMM as a guide.
2. Inspected spinner, bulkhead, hub and blades.
3. Lubricated propeller hub with Aeroshell 6 grease IAW 115N 61-00-15.
4. ADs current to biweekly revision 2018-21.
5. Performed ground run operational and leak check.

I certify this propeller has been inspected IAW an 100HR Inspection and was determined to be in airworthy condition.

Authorized Signature

JUSTIN CONNELL AP3290243 IA



Date: 01/07/19 N176DS S/N: 40.376
Propeller: HC-C2YR-1BF S/N: NS4070B
Total Time: 126 Tach:3614.7 Hobbs:5010.4

MX Aero Global LLC
2901A E. Spring St. Long Beach, CA 90806
Main: 562.366.4806
Cell: 562.881.5345

1. Performed 100Hr inspection using DA40 AMM as a guide.
2. Inspected spinner, bulkhead, hub and blades.
3. ADs current to biweekly revision 2018-26
4. Performed ground run operational and leak check.

I certify this propeller has been inspected IAW a 100Hr inspection and was determined to be in airworthy condition.

Authorized Signature

Jorge Sanchez AP2761073 AP

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	---

N176DS

**Tom's Aircraft
LLC**

Phone 1-562-426-5331

DATE 03/11/2019

HC-C2YR-1BF
NS4070B

2721 E Spring Street * Long Beach Int'l Airport * Long Beach, CA 90806

FAX 1-562-426 1052

TACH 3960.8

WO# 19-229

PROPELLER LOG ENTRY


T TIME 202.1

3.1 Squawk Completed a Propeller 100HR / Annual Inspection using AC43-13 and the Cessna Service Manual as a reference.

3.2 AD2009-22-03 Hartzell propeller hub insp, Not Applicable by Hub SN#

This propeller has been inspected in accordance with a 100HR/annual inspection as per FAR PART 43 APPENDIX D. This inspection used the DIAMOND DA-40 service manual as a reference. This propeller was found to be in an airworthy condition. Ran the aircraft. All systems ops check good. This Propeller is approved for return to service.

FRANCIS SALISBURY



FAA REPAIR STATION VTMR569K
